⚠ 📖

(SK) 3M™ VFlex™ Časticový respirátor
(SI) 3M™ VFlex™ Respirator za delce
(IL) 3M™ VFlex™ נשמית חלקיקים
(EE) 3M™ VFlex™ Tolmurespiraator
(LV) 3M™ VFlex™ Daļiņu respirators
(LT) 3M™ VFlex™ Respiratorius nuo dalelių
(RO) 3M™ VFlex™ Masca de protectie impotriva particulelor
(RU)(BY)(AZ) 3M™ VFlex™ Полумаска фильтрующая для защиты от аэрозолей
(UA) 3M™ VFlex™ Протиаерозольний респіратор
(HR) 3M™ VFlex™ Respirator za čestice
(BG) 3M™ VFlex™ Респиратор за частици
(RS) 3M™ VFlex™ Respirator za čestice
(TR) 3M™ VFlex™ Partikül Maskesi
(KZ) 3M™ VFlex™ Аэрозольдерден қорғауға арналған жартылай маска
(AU)(NZ) 3M™ VFlex™ Particulate Respirator

www.3M.EU/Safety

3M

34-8721-9193-6

⚠ 📖

(GB)(IE)(ZA)(AE) 3M™ VFlex™ Particulate Respirator
(FR)(CH)(BE) 3M™ VFlex™ Masque antipoussières
(DE)(CH)(AT) 3M™ VFlex™ Partikelmaske
(IT)(CH) 3M™ VFlex™ Respiratore per Polveri
(ES) 3M™ VFlex™ Mascarilla para partículas
(NL)(BE) 3M™ VFlex™ Stofmasker
(SE) 3M™ VFlex™ Filtrerande halvmask
(DK) 3M™ VFlex™ Støvmaske
(NO) 3M™ VFlex™ Støvmaske
(FI) 3M™ VFlex™ Hiukkassuojain
(IS) 3M™ VFlex™ öndunarhlíf fyrir agnir
(PT) 3M™ VFlex™ Máscara para Partículas
(GR) 3M™ VFlex™ Μάσκα Σωματιδίων
(PL) 3M™ VFlex™ Półmaska filtrująca
(HU) 3M™ VFlex™ Részecskeszűrő félálarc
(CZ) 3M™ VFlex™ Filtrační polomaska proti částicím

www.3M.EU/Safety

3M



Figure 1./Figure 1./Abbildung 1./Figura 1./Figura 1/Afbeelding 1./Figur 1./Figur 1./Figur 1./Kuva 1./Mynd 1./Figura 1./Εικόνα 1./Rys. 1./1. ábra./ Číslo 1./Obrázok 1./Slika 1./ איור 1/Joonis 1./1. attēls/1 pav./Figura1./ Рис. 1./Малюнок 1./Слика 1./Фигура 1./Crtež 1./Şekil 1./Сурет1.

3M United Kingdom PLC
3M Centre, Cain Road
Bracknell, RG12 8HT
0870 60 800 60

3M Ireland
The Iveagh Building, The Park
Carrickmines, Dublin 18
1 800 320 500

3M South Africa
146a Kelvin Drive, Woodmead
Sandton 2128, Johannesburg
+27 11 806 2230

3M Gulf Ltd.
P.O. Box 20191
Building 11, Third Floor, Dubai
Internet City, Deira
+ 971 4 367 0777

3M Egypt Trading Ltd.
Sofitel Tower, 19th Floor,
Corniche el-Nil St. Maadi, Cairo
+202 2525 9007

3M France
Bd de l'Oise
95006 Cergy Pontoise Cedex
+33 1 30 31 61 61

3M (Schweiz) GmbH,
Eggstrasse 93, Postfach,
8803 Rüschlikon, Switzerland,
Tel: 044 724 90 90.

3M Belgium bvba/sprl
Hermeslaan 7
1831 Diegem
+32 2 722 51 11

3M Deutschland GmbH
Carl-Schurz-Str. 1
41453 Neuss
+49 2131 14 26 04

3M Österreich GmbH
Kranichberggasse 4
1120 Wien
+43 1 86686 0

3M Italia srl
Via Norberto Bobbio 21
20096 Pioltello (MI)
+39 02 70351

3M España,S.L.
Juan Ignacio Luca de Tena, 19-25
28027 Madrid
+34 91 321 62 81

3M Nederland B.V.
Molengraaffsingel 29
2629 JD Delft
+31 (0)15 7822406

3M Svenska AB
Bollstanäsvägen 3
191 89 Sollentuna
+46 8 92 21 00

3M (Denmark) a/s
Hannemanns Allé 53
DK 2300 København S
+45 43480100

3M Norge AS
Tærudgata 16
Postboks 300, 2001 Lillestrøm.
Tlf: 06384

Suomen 3M Oy
PL 600 (Keilaranta 6)
02151 Espoo
p. +358 9 525 21

Tengiliður á Íslandi:
Hannemanns Allé 53
DK 2300 København S
+45 43480100

3M España, S.L., Sucursal em Portugal, Lda Edifício Office Oriente
Rua do Mar da China, nº 3 - 3º Piso A.
1990-138 Lisboa.
+351 21 313 4500

3M Hellas MEPE
Κηφισίας 20,
151 25, Μαρούσι, Αθήνα, Ελλάδα
+30 210 68 85 300

3M Poland Sp. z o.o.
Aleja Katowicka 117, Kajetany K / Warszawy
05-830 Nadarzyn
+48 22 739 60 00

3M Hungária Kft.
Infopark E Épület, 1117
Budapest
Neumann János utca 1/E
+36 1 270 7777

3M Česko, s.r.o.
V Parku 2343/24
148 00 Praha 4
+420 261 380 111

3M Slovensko s.r.o.
Polus Tower II, Vajnorská 100/B,
831 04 Bratislava, Slovensko
Tel: +421 249 105 211

3M (East) AG
Podružnica v Ljubljani
Cesta v Gorice 8, SI-1000 Ljubljana
+386 1 2003 630

3M ישראל בע"מ
רחוב מדינת היהודים 91
ת.ד. 2042 - הרצליה 46120
+972 9 961 5000

3M Eesti OÜ
Pärnu mnt. 158
11317 Tallinn
+372 6 115 900

3M Latvija SIA,
K. Ulmaņa gatve 5,
Rīga, LV-1004
+371 67 066 120

3M Lietuva
A. Goštauto g. 40A
LT-03163 Vilnius
+370 5 216 07 80

3M România
Bucharest Business Park, Str.
Menuetului 12, cladirea D, et.3,
013713 Bucharest
+40 21 2028000

3M Россия
121614, Москва,
ул. Крылатская, д. 17, стр. 3,
Б.Ц. «Крылатские Холмы»
+7 495 784 74 74

Представительство 3М в Беларуси, Бизнес-центр "Омега Тауэр", 5й этаж
Пр-т Дзержинского, 57
220089 а/я 23 Минск, Беларусь
+375 17 372 70 06

3M (East) AG
"BRIDGE Plaza" 4th floor, 12
Bakikhanov street
Baku AZ 1065
+994 12 404 5050

3M Україна
Бізнес-центр "Горизонт Парк", 7
пов., вул. М. Амосова, 12, Київ
03680, Київ, Україна
тел. (044) 490 57 77.

3M (EAST) AG PODRUŽNICA RH
Avenija Večeslava Holjevca 40
10010 Zagreb
+385 1 2499 750

3M България
Младост 4, бизнес парк София,
сграда 4, етаж 2
1766 София, България
тел: 02/9601911, факс 02/9601926

3M Representation Office Beograd
Milutina Milankovica 23
11070 Novi Beograd
+381 11 3018459

3M Turkey
Sehit Sinan Eroglu Cad. Akel Is
Merkezi, No: 6, A Blok
34805 Kavacık / Beykoz/
ISTANBUL-TURKEY
+90 216 538 07 77

3M Қазақстан ЖШС
Қазақстан Республикасы,
050051 Алматы қ., «Көктем-2»
бизнес-орталығы,
Фонвизин к-сі 17А, 3-ші қабатты,
тел.: +7 727 333 0000,
факс: +7 727 333 0001

3M Australia Pty Limited
1 Rivett Road, North Ryde
N.S.W. 2113
+61 (1)800 024 464

3M New Zealand Limited
94 Apollo Drive, Rosedale
AUCKLAND 0632, New Zealand
+64 (0)800 364 357

ITA181640/1217 © 3M

(GB)(IE)(ZA)(AE) These products meet the requirements of EN149:2001+A1:2009, filtering facepiece respirators for use against particles. They should be used to protect the wearer from solid and non-volatile liquid particles only.

⚠ **Particular attention should be given to warning statements where indicated.**

⚠ WARNINGS AND LIMITATIONS

Always be sure that the complete product is:
- Suitable for the application;
- Fitted correctly;
- Worn during all periods of exposure;
- Replaced when necessary.

• **Proper selection, training, use and appropriate maintenance are essential in order for the product to help protect the wearer from certain airborne contaminants. Failure to follow all instructions on the use of these respiratory protection products and/or failure to properly wear the complete product during all periods of exposure may adversely affect the wearer's health, lead to severe or life threatening illness or permanent disability.**
• For suitability and proper use follow local regulations and refer to all information supplied. For more information contact a safety professional or 3M on 0870 60 800 60 (UK) or 1800 320 500 (Ireland).
• Before use, the wearer must be trained in use of the complete product in accordance with applicable Health and Safety standards/guidance.
• These products do not contain components made from natural rubber latex.
• These products do not protect against gases/vapours.
• Do not use in atmospheres containing less than 19.5% oxygen. (3M definition. Individual countries may apply their own limits on oxygen deficiency. Seek advice if in doubt).
• Do not use for respiratory protection against atmospheric contaminants/concentrations which are unknown or immediately dangerous to life and health (IDLH).
⚠ **Do not use with beards or other facial hair that may inhibit contact between the face and the product thus preventing a good seal.**
• Leave the contaminated area immediately if:
a) Breathing becomes difficult.
b) Dizziness or other distress occurs.
• Discard and replace the respirator if it becomes damaged, breathing resistance becomes excessive or at the end of the shift.
• Do not alter, modify, clean or repair this respirator.
• In case of intended use in explosive atmospheres, contact 3M.
• Before initial use, always check that the product is within the stated shelf life (use by date).
• Dispose in accordance with local regulations

FITTING INSTRUCTIONS

Select most appropriate size from the 2 sizes of respirator available.
9152 is suggested for the majority of users.
9152S is suggested for users with small faces.
Figure 1.
Before fitting device, ensure hands are clean.
All respirator components should be inspected for damage prior to each use.
1. Using both hands, place fingers on the top side and thumbs on the underside of noseclip. Bend slightly at centre of noseclip.
2. Unfold the respirator by pulling top and bottom panels open to form a cup shape. Straps should be held on the top panel.
3. Cup respirator in one hand with open side towards face. Hold respirator under chin, with noseclip up.
4. Locate one strap below the ears, then the other strap across the crown of the head. Straps must not be twisted.
Adjust top and bottom panels for a comfortable fit, ensuring edges are not folded in and bottom panel is securely under the chin. Tabs on side of respirator (marked 'A' in Figure 1 step 2) may be used to comfortably adjust respirator.
5. Using both hands, mould noseclip to the shape of the nose to ensure a close fit and good seal. Pinching the noseclip using only one hand may result in less effective respirator performance.
6. The seal of the respirator on the face should be fit-checked before entering the workplace.

FIT CHECK

1. Cover the front of the respirator with both hands being careful not to disturb the fit of the respirator.
2a) UNVALVED respirator - EXHALE sharply;
2b) VALVED respirator - INHALE sharply.
3. If air leaks around the nose, re-adjust the noseclip to eliminate leakage. Repeat the above fit check.
4. If air leaks at the respirator edges, work the straps back along the sides of the head to eliminate leakage. Repeat the above fit check.
If you CANNOT achieve a proper fit DO NOT enter the hazardous area. See your supervisor.
Users should be fit tested in accordance with national requirements.
For information regarding fit testing procedures, please contact 3M.

STORAGE AND TRANSPORTATION

Store in accordance with manufacturer's instructions, see packaging.
NOTE Average conditions may exceed 25°C / 80% RH for limited periods.
They can reach an average of 38°C / 85% RH, provided that this is for no more than 3 months in the shelf life of the product. Before initial use, always check that the product is within the stated shelf life (use by date).
When storing or transporting this product use original packaging provided.
Do not store in direct sunlight.

MARKING

NR = Non reusable (single shift use only), D = Meets the clogging requirements ⏳ End of Shelf Life, Date format: YYYY/MM/DD, 🌡 Temperature Range, ☂ Maximum Relative Humidity.

APPROVALS

These products are type approved by INSPEC International Limited, 56 Leslie Hough Way, Salford, Greater Manchester M6 6AJ, UK (Notified Body number 0194). and audited annually by BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP, UK, Notified Body No. 0086. These products are CE Marked to the requirements of Community Directive 89/686/EEC or European Regulation (EU) 2016/425. The applicable legislation can be determined by reviewing the Certificate and Declaration of Conformity at www.3m.com/Respiratory/certs.

(FR)(CH)(BE) Ces produits répondent aux exigences de la norme EN149:2001+A1:2009, demi-masques filtrants contre les particules. Ils peuvent être utilisés comme protection contre des aérosols solides et liquides non-volatils.

⚠ **Une attention particulière doit être portée aux limites d'utilisations indiquées.**

⚠ AVERTISSEMENTS ET LIMITES

Toujours s'assurer que le produit:
- Convient à l'application pour laquelle il est utilisé;
- Est correctement porté;
- Est porté pendant toute la durée d'exposition au risque;
- Est changé dès que nécessaire.

• **Un choix correct, une formation, une utilisation et une maintenance appropriées sont essentiels pour que le produit puisse protéger l'utilisateur contre certains contaminants atmosphériques. Le non-respect de toutes les instructions relatives à l'utilisation de ces produits et/ou le non-respect du port correct de cet appareil pendant toute la période d'exposition peut nuire à la santé de l'utilisateur et provoquer une maladie grave ou une invalidité permanente.**
• Pour une utilisation adéquate et acceptable, se référer aux recommandations locales en vigueur et aux informations fournies. Pour plus d'information, contacter un professionnel de la sécurité ou votre représentant 3M.
• L'utilisateur devra avoir reçu une formation préalable à la bonne utilisation du produit en accord avec les exigences essentielles de santé et de sécurité en vigueur.
• Ce produit ne contient pas de composant à base de caoutchouc naturel (latex).
• Ce produit ne protège pas le porteur contre les gaz ou les vapeurs.
• Ne pas utiliser dans des atmosphères contenant moins de 19,5 % d'oxygène (définition 3M. Chaque pays peut appliquer ses propres limites en matière d'insuffisance en oxygène. En cas de doute, demandez conseil).
• Ne pas utiliser comme protection respiratoire lorsque la concentration en contaminants est inconnue ou présente un danger immédiat pour la vie ou la santé.
⚠ **A ne pas utiliser si vous portez une barbe ou toute autre pilosité faciale qui pourrait empêcher un contact parfait entre le visage et le bord du masque.**
• Quitter immédiatement la zone contaminée si :
a) La respiration devient difficile.
b) Des vertiges ou d'autres troubles apparaissent.
• Jeter et remplacer le masque si celui-ci est endommagé ou si la résistance respiratoire devient excessive ou à la fin d'un poste de travail
• Ne pas altérer, modifier, nettoyer ou réparer ce masque
• Dans le cas d'une utilisation en atmosphère explosible, contacter 3M.
• Avant d'utiliser le produit pour la première fois, s'assurer que la date de validité n'est pas dépassée (date limite d'utilisation).
• Mettre au rebut conformément aux réglementations locales en vigueur.

INSTRUCTIONS DE MISE EN PLACE

Choisir la taille la plus appropriée entre les 2 tailles des masques respiratoires disponibles.
9152 taille standard
9152S est suggéré pour les utilisateurs ayant un visage fin
Schéma 1.
Avant de mettre l'équipement, assurez-vous que vos mains soient propres.
Chaque masque de protection respiratoire doit être inspecté pour tout dommage avant chaque utilisation.
1. En utilisant vos deux mains, placer les doigts sur la partie supérieure et le pouce sous la barrette nasale. L'incurver en son centre.
2. Déplier le masque en ouvrant les parties inférieures et supérieure pour former une coque. Les élastiques doivent reposer sur la partie supérieure.
3. Incurver le masque dans une main, la partie ouverte vers le visage. Tenir le masque sous le menton, la barrette nasale orientée vers le haut.
4. Placer un élastique sous les oreilles, l'autre sur le sommet plat du crâne. Les élastiques ne doivent pas être enroulés.
Ajuster les parties supérieure et inférieure du masque pour assurer une étanchéité confortable, en s'assurant qu'elles ne sont pas repliées et que la partie inférieure repose bien sous le menton. Les languettes sur le côté du masque (marquées "A" sur la figure 1, étape 2) peuvent être utilisées pour ajuster confortablement le masque.
5. Adapter la barrette nasale à la forme du nez avec les deux mains. Il est important de réaliser cette opération à l'aide des deux mains pour assurer une parfaite étanchéité et obtenir l'efficacité attendue.
6. L'étanchéité du masque au visage devra être vérifiée avant d'entrer dans la zone de travail.

VERIFICATION DE L'AJUSTEMENT

1. Placer les deux mains en coquille sur le masque sans le déplacer.
2. a) Masque sans soupape - EXPIRER très fortement;
2. b) Masque avec soupape - INSPIRER très fortement.
3. Si de l'air fuit sur les contours du nez, réajuster la barrette nasale pour éliminer les fuites. Refaire un test d'étanchéité.
4. Si de l'air fuit sur le pourtour du masque, ramener les élastiques vers l'arrière. Refaire un test d'étanchéité.
Si une étanchéité satisfaisante NE PEUT PAS être obtenue, NE PAS pénétrer dans la zone contaminée.
Consulter votre responsable.
L'utilisateur doit réaliser un test d'étanchéité en accord avec les recommandations locales en vigueur.
Pour des informations concernant les procédures de vérification de l'étanchéité, merci de contacter 3M.

STOCKAGE ET TRANSPORT

Stocker suivant les instructions mentionnées par le fabricant. Se reporter à l'emballage.
REMARQUE Les conditions moyennes de température et d'humidité ne doivent pas dépasser 25°C / 80% RH (Humidité Relative) au-delà de courtes périodes.
Elles peuvent atteindre 38°C / 85% RH pourvu que cela ne dépasse pas 3 mois pendant la période de stockage. Avant d'utiliser le produit pour la première fois, s'assurer que la date de validité n'est pas dépassée (date limite d'utilisation). Stocker et transporter le produit dans son emballage d'origine fourni. Ne pas exposer directement à la lumière du soleil.

MARQUAGE

NR = Non Réutilisable (un poste de travail seulement), D= Passe le test de colmatage ⏳ Fin de la durée de vie, Format de la date: AAAA/MM/JJ, 🌡 Intervalle de températures, ☂ Humidité relative maximale.

HOMOLOGATIONS

Ces produit sont approuvés Type par INSPEC International Limited, 56 Leslie Hough Way, Salford, Greater Manchester M66AJ, UK (laboratoire notifié numéro 0194). Et audité annuellement par BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK58PP, UK, laboratoire notifié numéro 0086. Ces produits sont marqués CE suivant les exigences de la Directive Européenne 89/686/CEE ou suivant le Règlement Européen (EU) 2016/425. La législation applicable est mentionnée sur la Déclaration de Conformité et le Certificat disponible sur www.3m.com/Respiratory/certs

(NO) Disse produktene møter kravene i EN 149:2001+A1:2009, filtrerende halvmaske mot partikler. De skal kun brukes for å beskytte brukeren mot faste- og ikke flyktige væskeformige partikler.

⚠ **Det må vises særlig oppmerksomhet der advarsler forekommer.**

⚠ ADVARSLER OG BEGRENSNINGER

Vær alltid sikker på at produktet:
- er egnet for oppgaven
- er riktig tilpasset
- blir brukt i hele eksponeringstiden
- blir byttet ut når det er nødvendig

(AU)(NZ) These products meet the requirements of EN149:2001+A1:2009, filtering facepiece respirators for use against particles. They should be used to protect the wearer from solid and non-volatile liquid particles only.

⚠ **Particular attention should be given to warning statements where indicated.**

⚠ WARNINGS AND LIMITATIONS

Always be sure that the complete product is:
- Suitable for the application;
- Fitted correctly;
- Worn during all periods of exposure;
- Replaced when necessary.

• **Proper selection, training, use and appropriate maintenance are essential in order for the product to help protect the wearer from certain airborne contaminants. Failure to follow all instructions on the use of these respiratory protection products and/or failure to properly wear the complete product during all periods of exposure may adversely affect the wearer's health, lead to severe or life threatening illness or permanent disability.**
• For suitability and proper use follow local regulations, refer to all information supplied or contact an occupational hygienist, safety professional or 3M representative on the Tech Assist Helpline 3M Australia 1800 024 464, 3M New Zealand 0800 364 357.
• Before use, the wearer must be trained in use of the complete product in accordance with applicable Health and Safety standards/guidance.
• These products do not contain components made from natural rubber latex.
• These products do not protect against gases/vapours.
• Do not use in atmospheres containing less than 19.5% oxygen. (3M definition. Individual countries may apply their own limits on oxygen deficiency. Seek advice if in doubt).
• Do not use for respiratory protection against atmospheric contaminants/concentrations which are unknown or immediately dangerous to life and health (IDLH).
⚠ **Do not use with beards or other facial hair that may inhibit contact between the face and the product thus preventing a good seal.**
• Leave the contaminated area immediately if:
a) Breathing becomes difficult.
b) Dizziness or other distress occurs.
• Discard and replace the respirator if it becomes damaged, breathing resistance becomes excessive or at the end of the shift.
• Do not alter, modify, clean or repair this respirator.
• In case of intended use in explosive atmospheres, contact 3M.
• Before initial use, always check that the product is within the stated shelf life (use by date).
• Dispose in accordance with local regulations

FITTING INSTRUCTIONS

Select most appropriate size from the 2 sizes of respirator available.
9152 is suggested for the majority of users.
9152S is suggested for users with small faces.
Figure 1.
Before fitting device, ensure hands are clean.
All respirator components should be inspected for damage prior to each use.
1. Using both hands, place fingers on the top side and thumbs on the underside of noseclip. Bend slightly at centre of noseclip.
2. Unfold the respirator by pulling top and bottom panels open to form a cup shape. Straps should be held on the top panel.
3. Cup respirator in one hand with open side towards face. Hold respirator under chin, with noseclip up.
4. Locate one strap below the ears, then the other strap across the crown of the head. Straps must not be twisted.
Adjust top and bottom panels for a comfortable fit, ensuring edges are not folded in and bottom panel is securely under the chin. Tabs on side of respirator (marked 'A' in Figure 1 step 2) may be used to comfortably adjust respirator.
5. Using both hands, mould noseclip to the shape of the lower part of the nose to ensure a close fit and good seal. Pinching the noseclip using only one hand may result in less effective respirator performance.
6. The seal of the respirator on the face should be fit-checked before entering the workplace.

FIT CHECK

1. Cover the front of the respirator with both hands being careful not to disturb the fit of the respirator.
2a) UNVALVED respirator - EXHALE sharply;
2b) VALVED respirator - INHALE sharply.
3. If air leaks around the nose, re-adjust the noseclip to eliminate leakage. Repeat the above fit check.
4. If air leaks at the respirator edges, work the straps back along the sides of the head to eliminate leakage. Repeat the above fit check.
If you CANNOT achieve a proper fit DO NOT enter the hazardous area. See your supervisor.
It is recommended that wearers should be fit tested in accordance with AS/NZS 1715.
For information regarding fit testing procedures, please contact 3M.

STORAGE AND TRANSPORTATION

Store in accordance with manufacturer's instructions, see packaging.
NOTE Average conditions may exceed 25°C / 80% RH for limited periods. They can reach an average of 38°C / 85% RH, provided that this is for no more than 3 months in the shelf life of the product. Before initial use, always check that the product is within the stated shelf life (use by date).
When storing or transporting this product use original packaging provided.
Do not store in direct sunlight.

MARKING

NR = Non re-usable (single shift use only), D = Meets the clogging requirements ⏳ End of Shelf Life, Date format: YYYY/MM/DD, 🌡 Temperature Range, ☂ Maximum Relative Humidity.

APPROVALS

These products are type approved by INSPEC International Limited, 56 Leslie Hough Way, Salford, Greater Manchester M6 6AJ, UK (Notified Body number 0194). and audited annually by BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP, UK, Notified Body No. 0086. These products are CE Marked to the requirements of Community Directive 89/686/EEC or European Regulation (EU) 2016/425. The applicable legislation can be determined by reviewing the Certificate and Declaration of Conformity at www.3m.com/Respiratory/certs.

Itarus House, Tenter Road, Moulton Park, Northampton, NN3 6PZ
itarus Simplifying Complexity...
Need help? Contact us: +44 (0)1604 468100 mail@itarus.com www.itarus.com

Print Spec. No.:	34-8721-9193-6
Stock No.:	N/A
SAP No.:	N/A
Structure Spec.:	
Title:	PSD - V-Flex Pandemic FFP2 Respirator - UI - SLG
Job No.:	181640
File No.:	61258
Asset No.:	15673
File Name:	O-AICC17-MAC10-34-8721-9193-6.ai
Revision date:	08/12/2017
Revision time:	09:03
Barcode:	
Size/BWR:	N/A% / 000
Dimensions:	507 x 708 mm / 19.961 x 27.874 in
Folded Size:	XX x XX mm / XX x XX in
Colours: 1	Black
Technical Colours:	Die Line
Operator:	27
UIC:	TmK7XQ
Version:	1
Region:	0
itarus:	0

Powered by OnlineServices
Industry Partner
Microsoft CERTIFIED Partner

708mm / 27.87”
118mm / 4.64”
507mm / 19.96”
72.428mm / 2.85”